Date:	Property is: Single Fan 8/24/2010	nily X Duple	x Other	
take no respo	onsibility for problems discovered a	after the inspection d	es. The City of Milwaukee, the Redevelopment Authority, ate, or for omissions through error or oversight. The list doderal Block Grant or HOME programs.	
Exterior (Condition Report			
Location	Required Work		Note/Comments	Cost
Site	Landscaping	n/a Yes x	Increase grade around foundation	\$ 450.00
	Steps/Handrails	n/a X Yes		\$
	Service walks	n/a Yes X	Service walk concrete slabs broken multiple areas	\$ 1,400.00
	Fencing	n/a X Yes		\$
	Parking	n/a X Yes		\$
	Retaining walls	n/a X Yes		\$
	Other	n/a X Yes		\$
	Other	n/a X Yes]	\$
Garage	Shingles: repair	n/a X Yes]	\$
	Shingles: Roof over existing	n/a X Yes		\$
	Shingles:Tear off & re-roof	n/a X Yes		\$
	Gutters/downspouts	n/a X Yes		\$
	Flashing	n/a X Yes		\$
	Eaves	n/a X Yes		\$
	Siding	n/a X Yes		\$
	Doors	n/a X Yes	1	\$
	Windows	n/a X Yes	7	\$
	Slab	n/a X Yes	7	\$
	Paint	n/a X Yes	7	\$
	Electrical	n/a X Yes	7	\$
Porches	Other	n/a Yes]	\$
	Roof	n/a X Yes	1	\$
	Deck-upper	n/a X Yes		\$
	Decklower	n/a X Yes	7	\$
	Steps/handrails	n/a Yes X	Front steps missing handrail	\$ 450.00
	Ceiling	n/a X Yes		\$
	Guardrails	n/a X Yes		\$
	Structural	n/a X Yes		\$
	Paint	n/a 🗓 Yes 🗆		\$

n/a Yes

Other

\$

House

Chimney	n/a X Yes	\$
Shingles: repair	n/a X Yes	\$
Shingles: Roof over existing	n/a X Yes	\$
Shingles:Tear off & re-roof	n/a X Yes	\$
Gutters/downspouts	n/a X Yes	\$
Flashing	n/a X Yes	\$
Eaves	n/a X Yes	\$
Siding	n/a X Yes	\$
Storm Doors	n/a X Yes	\$
Prime ("main") Doors	n/a Yes X Replace main rear door	\$ 650.00
Storm Windows	n/a X Yes	\$
Prime ("main") Windows	n/a X Yes	\$
Paint	n/a Yes X Several areas peeling paint	\$ 750.00
Foundation	n/a X Yes	\$
Electrical	n/a X Yes	\$
Other	n/a Yes	\$
Other	n/a Yes	\$
Other	n/a Yes	\$
Other	n/a Yes	\$

Exterior: Estimated Cost:* \$
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

3,700.00

Interior Co	ondition Report					_	
	Unit: Entire unit (single family) Upper unit of duplex	X				Lower unit of duplex Other	
Mechanical Heating	Required Work	Ш				Office	
_	Repair/replace boiler	n/a >	Κ,	Yes			\$
	Repair radiation	n/a >	Κ,	Yes			\$
	Repair/replace furnace	n/a	ζ,	Yes			\$
	Repair ductwork	n/a 🕽	Κ,	Yes			\$
	Replace thermostat	n/a >	ζ,	Yes			\$
	Repair/replace grilles	n/a >	ζ,	Yes			\$
- 1	Tune boiler/furn. insp ht exchange	n/a	Κ,	Yes			\$
Electrical	Repair/replace receptacles	n/a 🕽	Κ,	Yes			\$
	Repair/replace switches	n/a >	ζ,	Yes			\$
	Repair/replace fixtures	n/a	ζ,	Yes			\$
	Install outlets and circuits	n/a >	ζ,	Yes			\$
	Install outlets and circuits	n/a	ζ,	Yes			\$
	Install outlets and circuits	n/a >	ζ,	Yes			\$
	Install outlets and circuits	n/a >	ζ,	Yes			\$
	Upgrade service	n/a >	ζ,	Yes			\$
	Other	n/a		Yes			\$
	Other	n/a		Yes			\$
Plumbing	Repair/replace kitchen sink	n/a 🕽	ζ,	Yes			\$
	Repair/replace kitchen sink fauce	in/a	ζ,	Yes			\$
	Repair/replace tub	n/a	ζ,	Yes			\$
	Repair/replace tub faucet	n/a 🕽	Κ,	Yes			\$
	Repair/replace toilet	n/a	Κ,	Yes			\$
	Repair/replace lavatory	n/a 🕽	ζ,	Yes			\$
	Repair/replace lavatory faucet	n/a	ζ,	Yes			\$
	Repair/replace wash tub	n/a	ζ,	Yes			\$
	Repair/replace wash tub faucet	n/a	ζ,	Yes			\$
	Unclog piping:	n/a	ζ,	Yes			\$
	Repair drain/waste/vent piping	n/a 🕽	ζ,	Yes			\$
	Repair water piping	n/a		Yes	Х	Several areas leaking	\$ 550.00
	Repair/replace water heater	n/a		Yes	Χ	Replace one water heater	\$ 650.00
	Other	n/a		Yes			\$

\$

n/a Yes

Other

				Total Exterior and Interior Cost:*	\$	10,250.00
				Interior: Estimated Cost:	\$	6,550.00
		n/a Yes	s 🗌		\$	
		n/a Yes	s 🗌		\$	
		n/a Yes	s 🗌		\$	
		n/a Yes	s 🗌		\$	
Other	Repair defective	n/a Yes	\$ [X]	Several floor coverings need replacing	\$	2,300.00
Floors	5	, 🗆			•	
Stairs	Repair defective	n/a Yes	• [X]	Several steps broken to basement	\$	450.00
Handrails	Repair/replace defective	n/a Yes	s [X]	Handrail to 2nd floor broken, missing to basement	\$	400.00
	Install smoke alarm: 2nd flr.	n/a X Yes	; 🔲	Self Help	\$	
	Install smoke alarm: 1st flr.	n/a X Yes	s 🗌	Self Help	\$	
riie Salety	Install smoke alarm:bsmt.	n/a X Yes	s 🗌	Self Help	\$	
Fire Safety	Tropan or ropin of delicente	.,,	, [X]		<u> </u>	
Paint	Repair or repl. @ defective	n/a Yes	s 🔽	Fresh paint several areas needed	\$	400.00
·	Repair or repl. @ defective	n/a Yes	X	Several areas damaged drywall	\$	550.00
Walls/Ceiling	Repair or repl. locks/latches	n/a Yes	5 [X]	Several missing	\$	200.00
	Repair or replace doors	n/a Yes		Several damaged	\$	800.00
Doors	rtopan or ropiace each	.,α [χ] .σ.			Ψ	
	Repair or replace sash	n/a X Yes	, [<u> </u>	\$	
Windows	Replace broken glass	n/a Yes	s [X]	Several broken glass	\$	250.00
Windows						

Prepared by: Jeff Moser, Advantage Home Inspection Services Date: 8/24/2010

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.